

<b>SB Number:</b>	<b>SB 2H7-001</b>	<b>Creation Date: 04/08/2009</b>
<b>Subject:</b>	<b><i>Kyocera recommended compact flash cards are not recognized</i></b>	
<b>Model:</b>	<b>TASKalfa250ci/300ci/400ci/500ci</b>	

<b>Phenomenon</b>	<p>The following compact flash cards recommended by Kyocera, may not be recognized.</p> <ul style="list-style-type: none"> <li>• <b>Kingston</b> CF/32, CF/24, CF/16 and CF/8 (Number after the “/” is the CF capacity in MB)</li> <li>• <b>SST</b> SST48CF032, SST48CF016 and SST48CF008 (number after the “CF” is the CF capacity in MB)</li> </ul>
-------------------	---

<b>Solution</b>	The capacitor C53 at the PWB KUIO IF has been changed to make sure that the power source on the KUIO PCB boots up, after the power source at the main PCB is finished booting.
-----------------	--

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
					Old	New	Old	New	
	1	302H794030 2H794030	302H794031 2H794031	PARTS PWB KUIO IF ASSY SP	1	1	O	O	O

<b>Classification</b>	<input type="checkbox"/> Entire stock rework <input type="checkbox"/> In-field modification at next visit <input type="checkbox"/> In-field modification by case <input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	<p>Please use other recommended CF cards then the ones mentioned above.          If the CF card you are using is among the CF cards mentioned above, please replace the parts PWB KUIO IF assy sp with.</p>

Affected serial numbers	Type	Serial number
	TASKalfa250ci/300ci/400ci/500ci	December 2008 production

Figure 29 Electrical Components 3 of the parts list

