

SB Number:	SB 2H7-032	Creation Date: 26/02/2010
Subject:	Clearing fuser related error codes such as CF186/C6100 etc.	
Model:	TASKalfa250ci/300ci/400ci/500ci	

Phenomenon	<p>Several fuser related error codes such as CF186 , C6100, C6200, C6030 or C6050 may occur under the following conditions:</p> <ol style="list-style-type: none"> 1. Firmware version 7.00 is installed on the machine. 2. Paper size is A4 or smaller. 3. Print-out is in duplex. 4. TASKalfa250ci/300ci paper output: Mailbox of the finisher (the phenomena will not occur when outputting to tray A/B/C or booklet). 5. TASKalfa400ci/500ci paper output: Finisher (tray A, mailbox or booklet) (the phenomena will not occur when outputting to tray B/C) 6. The phenomena may occur if the printing is interrupted due to one of the following reasons: <ul style="list-style-type: none"> • Paper empty. • Paper full, running out of staple, etc. in the finisher. • Toner empty. • Waste toner box is full. • Printing is interrupted by the user.
Solution	<p>This has been corrected in the following firmware:</p> <p>Main: 2H7_2F00.008.011 MMI: 2H7_7000.008.010</p>

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomena occur, please upgrade the firmware to the latest version.			

Serial numbers of affected machines

Type	Serial number
TASKalfa250ci/300ci/400ci/500ci	Not available