


# KYOCERA Service Bulletin

<b>SB Number:</b>	<b>SB 2H7-029</b>	<b>Creation Date:</b> 10/12/2009
<b>Subject:</b>	<b>Added seal fan front due to changed duct fan front</b>	
<b>Model:</b>	<b>TASKalfa250ci/300ci/400ci/500ci</b>	


<b>Contents of changes</b>	1. To improve the cooling process of ejected paper and to make the parts common with other models, the <b>duct fan front</b> has been changed. 2. To cover the gap of the <b>duct fan front</b> 302H733191 in order to prevent airflow leakage, the <b>seal fan front</b> 302H733780 has been added.
----------------------------	---

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	302H733190 2H733190	302H733191 2H733191	DUCT FAN FRONT	1	1	O	X	-
	2	-----	302H733780 2H733780	SEAL FAN FRONT	-	1	-	X	-

Old condition: Duct fan front 302H733190




New condition: Duct fan front 302H733191




The red marked segment has been removed.

New condition: Eject fan section



New condition: View from the back of the duct fan front



Align the seal according to the permitted margins (mm).

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
<b>Field measure</b>	To prevent airflow leakage, please attach the <b>seal fan front</b> 302H733780 to the <b>duct fan front</b> 302H733191, after cleaning the side of the <b>duct fan front</b> with cleaning alcohol.			

### Serial numbers of affected machines

Type	Serial number
TASKalfa250ci/300ci/400ci/500ci	Not available