


SB Number:	SB 2BJ-043	Creation Date: 12/06/2008
Subject:	Left cover feed has been changed to prevent paper Jam 21/22	
Model:	FS-9100DN/9120DN/9130DN/9520DN/9530DN/9500DN	

Phenomenon	Continuous feeding of paper by the PF-75 may result in paper Jam 21 or 22.
-------------------	--

Cause	This is caused by a sagging of the trail edge of the first sheet, resulting in that switch 2 mistakenly registers that this sheet has been fed through completely. Now the second sheet that's being fed may overlap with the first sheet of paper, resulting in the paper jam.
--------------	--

Solution	The left cover feed has been changed to prevent Jam 21 or 22. See below for further details.
-----------------	---

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
					Old	New	Old	New	
	1	302GR93161 2GR93161	302GR93162 2GR93162	PARTS VERTICAL FEED UNIT	1	1	X	O	O
	2	302BL06101 2BL06101	302BL06102 2BL06102	LEFT COVER FEED	1	1	2	O	O



Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
Field measure	Replace left cover feed 302BL06101 with 302BL06102.			

Affected serial numbers	Type FS-9100DN/9120DN/9130DN/9520DN/ 9530DN/9500DN	Serial number From the production of March 2008
--------------------------------	---	---