

# KYOCERA Service Bulletin


<b>SB Number:</b>	<b>SB 2G1-027</b>	<b>Creation Date:</b> 30/08/2010
<b>Subject:</b>	<b>Paper jam 00 due to the improper fitted bypass feed</b>	
<b>Model:</b>	<b>FS-9100DN/9500DN/9120DN/9520DN/9130DN/9530DN</b>	

Phenomenon	Paper jam 00 may occur.
Cause	The <b>front cover</b> is closed, while the <b>bypass feed</b> is improperly fitted.
Solution	The <b>sponge front</b> has been changed, so that the <b>bypass feed</b> will be properly fitted when closing the <b>front cover</b> .

The **sponge front** has been changed



	Old condition	New condition
Thickness	10mm	20mm
Colour	Grey	Black
Material	P.E A-8	Rubber sponge C-4305



## Parts

No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
				Old	New	Old	New	
1	2BL06620	302KS02110 2KS02110	SPONGE FRONT	1	1	X	O	O

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomenon occurs, please replace the <b>sponge front</b> with the latest type.			

## Serial numbers of affected machines

Type	Serial number
FS-9100DN/9500DN/9120DN/9520DN/9130DN/9530DN	July 2010 production.

The above mentioned changes have been applied to machines produced after the above mentioned production date.