

SB Number:	SB 2G1-012_ Revised issue	Creation Date: 28/08/2008
Subject:	Firmware upgrade (Jam 00 and 12 when using PF-750)	
Model:	FS-9130DN/9530DN	

Contents of changes	Item	Contents	
	1	Jam 12 when using the PF-750.	Jam 12 (no paper feed Jam) could occur when feeding paper from the PF-750 (especially in the duplex and cover mode)
	2	Machine keeps driving after print job is finished.	Machine could keep driving after finishing a Print job. The setting of the center thermistor has been changed to prevent this from happening.
	3	Jam 00 when selecting B5 paper size using the PF-750.	Selecting B5 paper size in the PF-750 using cover mode or duplex may result in error code Jam 00 (unknown paper Jam).

Latest firm-ware as of January 2008	Type	Program No.	Check SUM	Version	Status Date
	MAIN	S2G1_3000.007.001	D663	007.001	19/07/2007
	ENGINE	S2G1_1000.015.001	D6C5	015.001	21/12/2007

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When above mentioned phenomena occur, please upgrade al the firmware to the latest version.			

Affected serial numbers	Type	Serial number
	FS-9130DN	PAU8203431 and higher
	FS-9530DN	PAS8102901 and higher