

<b>SB Number:</b>	<b>SB 2DA-013</b>	<b>Creation Date:</b> 04/06/2007
<b>Subject:</b>	<b>Firmware upgrade, Scan to e-mail receiving error</b>	
<b>Model:</b>	<b>KM-1650/2050/2550</b>	

### Contents of change

Item	Contents
1 Measures against a receiving error in scan to E-mail	When continuously sending through Scan to E-mail, depending on timing, the mail Message-IDs (A part of the mail header information) are sometimes overlapped. Since some servers will not accept the same ID, the mail cannot be received and the data is lost. To resolve this error, each Message-ID will have a unique job number added.

### Current firmware specifications

Type	Program number	Check SUM	Version	Remarks
MAIN	2DA29178N	9CCF	Ver. 131	<b>New upgrade</b>
ENGINE	2FT29107N	85DC	Ver. 84	25 ppm machine
PRINTER FS	2DA_3F00.002.006	7EAE	Ver. 002.006	
LANGUAGE E	2DA29133E	1415	Ver. 24	

### Serial number information:

From the production of May 2007 onwards this firmware will be installed at the factory.