



Service Bulletin

Issued by Canon Europa N.V.

LBP

HARDWARE

Model:
LBP5200

Ref No.:
LBP-1320

Date:
April 2006

Location:

Service Parts

Subject:

Measure for image failure under strong light intensity

Detail:

There are cases where image failure (fogging) might occur when using this product under strong light intensity (e.g., when exposing it to direct sunshine).

As a preventive measure, a new SHIELD SHEET UNIT has been developed.

The SHIELD SHEET UNIT should be mounted on the top cover as described below.

RL1-1576-000



Service Part:

Part number: RL1-1576-000 SHIELD SHEET UNIT