



Service Bulletin

Issued by Canon Europa N.V.

Copier B/W

Software

Model:

iR5570

iR6570

Ref No.:

iR6570-009

(F1-T01-0M5-10027-01)

Date:

September, 2005

Location:

iR5570/6570 series DCON

Subject:

Releasing the DC-Controller Software (v21.01)

Reason:

The software has been upgraded, it is now offered as v21.01

T-1

[History of Updates]

Version	Description	Date
21.01	Correction of problem with drum memory	2005/09/26
20.05	1. K-size paper supported. 2. Modification of the error which remained the message on the LCD. 3. Modification of E001-0003 occurrence. 4. Modification of Service mode (DISPLAY > ANALOG > ABS-HUM)	-
11.02	1. The problem is fixed, such that an image density in the halftone area may become darker at the rear side of duplex. 2. The problem that a lifter alarm may not be canceled is fixed	-
10.04	First Version	-

Details:

Changes made when upgrading the DC-Controller to v21.01

T-2

No.	Item	Description
1-1	Correction of problem with drum memory	On rare occasions, drum memory may occur when an error occurs during the APC control. This problem is modified. Error is "E-Code" and "Door Open" etc.

Service Parts:

To be communicated as soon as identified.

Affected Machines:

To be communicated as soon as identified.