

<b>SB Number:</b>	<b>SB 2HP-006</b>	<b>Creation Date: 17/03/2008</b>
<b>Subject:</b>	<b><i>Firmware upgrade (Prevent JAM 18 and removing unused thermistor)</i></b>	
<b>Model:</b>	<b>FS-C8100DN</b>	

Contents of changes		
	Item	Contents
1	Method to prevent JAM 18 (Jam in vertical paper conveying section)	Due to a timing problem A JAM 18 error code may occur when using the second cassette.
2	Changes made to prevent a service call when removing unused transfer thermistor.	In order to remove an unused thermistor in the transfer belt unit, the firmware has been changed.

Latest firmware as of September 2007			
Type	Program No.	Check SUM	Version
MAIN	2HP_3000.005.003	8AEB	005.003
ENGINE	2HP_1000.010.001	180D	010.001