

<b>SB Number:</b>	<b>SB 2HP-018</b>	<b>Creation Date: 18/02/2009</b>
<b>Subject:</b>	<b>2 of the 4 fan's conveying 40 have been removed</b>	
<b>Model:</b>	<b>FS-C8100DN</b>	


<b>Contents of changes</b>	<p>The number of fan conveying 40's have been changed from 4 pcs to 2 pcs for manufacturing improvement.</p> <p><b>Based on this change please note the following:</b></p> <ul style="list-style-type: none"> <li>• 2 out of the 4 holes in the plate conv fan 302FZ24500 have been closed.</li> <li>• The seal fan conv, seal fan conv B, and duct conv up (attached to fan conveying 40) have been reduced from 4 pieces each to 2 pieces each in the machine.</li> </ul>
----------------------------	---

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	302FZ93510 2FZ93510	302FZ93511 2FZ93511	PARTS FEED UNIT ASSY	1	1	X	O	O
	2	302FZ44070 2FZ44070	302FZ44070 2FZ44070	+FAN CONVEYING 40	4	2	O	-	O
	3	-----	302JD24020 2JD24020	+DUCT CONV FRONT	-	1	-	X	-
	4	-----	302JD24030 2JD24030	+DUCT CONV REAR	-	1	-	X	-
	5	302FZ24510 2FZ24510	-----	+DUCT CONV UP	4	-	O	-	-
	6	-----	302JD24040 2JD24040	+SEAL FAN CONV	-	2	-	X	-
	7	302FZ24530 2FZ24530	-----	+SEAL FAN CONV	4	-	O	-	-
	8	302FZ24550 2FZ24550	302FZ24550 2FZ24550	+SEAL FAN CONV B	4	2	O	-	-

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	Please do not mix old with new parts when replacing the parts mentioned above. Mixing old with new parts may result in improper airflow.			

<b>Affected serial numbers</b>	<b>Type</b>	<b>Serial number</b>
	FS-C8100DN	May 2008 production

Old condition of plate conv fan 302FZ24500



New condition of plate conv fan 302FZ24500

