

Service Bulletin

Ref. No. :	SB-00137
Issue Date:	December 18, 2000
Model Name:	All models

1.Subject	2.Reason	3.Details	4.Serial No.	5.Interchangeability	6.Parts name & code
1.		Change of hook for parallel interface connector.			
3.		Hook for parallel interface connector is changed from spring hook to free hook. Position of the hook is changed free.			
4.		FS-1750 ALX0895067 ASR0805795			
		FS-3750 ALW0X20927 AYW0X6131 ASQ0902101 APR0904338	FS-5900C ALV0901143	FS-6700 ALR0806360 AMR0800482 AYR0X00212	
		FS-7000+ ALS0803643 AYS0800122 ASL0800326	FS-9000 ALT0802415 AMT0800549 AYT0800081 ASM0900251 APP0800235	FS-1000 AAA0848328 XHA0X00001 VYA0401200 VKA0802351 ASU0811229	FS-3800 AAC0800101
		Main board as serviceparts: running change after using up August, 2000 production stock.			
5.		Yes.			
6.		There is no change of part name and part code.			