

SB Number:	SB 2FP-011	Creation Date: 22/02/2006
Subject:	Firmware upgrade, Ver. A011 (engine)	
Model:	FS-3830N, FS-1920	

Firmware is upgraded as follows.

FS-3830N

For production efficiency, the system default value of engine parameter offset 5 (feed clutch timing) has been changed to 1. Previously it was manually set to 1 in the production process.

Type	Program number	Check SUM	Version	Remarks
ENGINE	EB21KA011	3B3D	A011	

FS-1920

1. For production efficiency, the system default value of engine parameter offset 5 (feed clutch timing) has been changed to 1. Previously it was manually set to 1 in the production process.
2. There is a possibility that the toner gauge will not work correctly. This has been corrected.

Type	Program number	Check SUM	Version	Remarks
ENGINE	EB20KA011	2A3A	A011	

Affected machine serial numbers:

FS-3830N: ALB5X69811 and higher

FS-1920: ALC5X24048 and higher