

<b>SB Number:</b>	<b>SB 2HG-001</b>	<b>Creation Date: 14/08/2009</b>
<b>Subject:</b>	<b><i>Firmware upgrade (engine version 003.002)</i></b>	
<b>Model:</b>	<b>FS-C5400DN</b>	

<b>Contents of changes</b>	As a measure against error code C6100, which has occurred on the production line, the engine firmware has been upgraded.
----------------------------	--

<b>Firmware</b>	<b>Type</b>	<b>Program No.</b>	<b>Check SUM</b>	<b>Version</b>	<b>Status Date</b>
	ENGINE	S2HG_1000003002	97d3	003.002	19/05/2009

<b>Field measure</b>	When the above mentioned phenomenon occurs, please upgrade the firmware to the latest version.
----------------------	--

<b>Affected serial numbers</b>	<b>Type</b>	<b>Serial number</b>
	FS-C5400DN	June 2009 production