

SB Number:	SB 2C9-012	Creation Date: 10/10/2004
Subject:	Changes to 'RIGHT, COVER'	
Model:	KM-1620	

Please be informed that the following changes have been implemented to improve the work efficiency for the attachment of the '**RIGHT COVER**' (No.1).



CONTENTS OF CHANGES

- 2 pieces of positioning boss have been added to the '**RIGHT COVER**'.
In compliance with the addition of the bosses, 2 positioning holes have been created in the scanner frame.
- The holes (4 places) in the '**RIGHT COVER**' for fixing the screws have been enlarged.
- The thickness of the rib has been increased to prevent the '**RIGHT COVER**' from deforming.

Field Measure

When attaching the new '**RIGHT, COVER**' (part no. 1 new) to a machine of an earlier production month than mentioned below, then please cut the 2 pieces of positioning boss ('A' in the fig. below) by a nipper etc., as there are no positioning holes on the old scanner frame for these bosses.

'RIGHT COVER' (No.1)



Parts Table

No.	Part No. OLD	Part No. NEW	Description	Q'ty Old New		Interchange ability	
1	2C904040	2C904041	RIGHT COVER	1	1	O	X

Affected Machine Serial Numbers:

KM-1620: production of November, 2003 and later