




<b>SB Number:</b>	<b>SB 2BJ-028</b>	<b>Creation Date:</b> 30/01/2004
<b>Subject:</b>	Firmware upgrade	
<b>Model:</b>	<b>KM-2530 / 3530, KM-4030</b>	

Please be informed that the firmware for KM-2530 / 3530 and KM-4030 has been upgraded as follows.

## CONTENTS OF CHANGES

	Item	Remarks						
1	Supporting Kyocera logo on the opening screen of operation panel.	Kyocera Mita logo displayed on the opening screen of liquid crystal operation panel is changed to Kyocera logo.						
2	Supporting Kyocera logo on network scanner web page	Kyocera Mita logo on scanner web page is changed to Kyocera logo.						
3	Fax output sheet is punched after print job is processed in punch mode.	In the condition of setting fax output destination to sub tray on 3,000 sheets finisher, after printer job is processed with punch mode, if fax data is printed, the fax output sheet is punched. => This problem is corrected.						
4	Message displayed on the operation panel in case of paper JAM has been adjusted.	<p>The following message and illustration are added to the operation LCD when removing the jammed paper with left cover opened.</p> <table><tr><td></td><td>Message</td></tr><tr><td><b>Before change</b></td><td>Paper jam</td></tr><tr><td><b>After change</b></td><td>Paper jam  Careful for Drum</td></tr></table>		Message	<b>Before change</b>	Paper jam	<b>After change</b>	Paper jam  Careful for Drum
	Message							
<b>Before change</b>	Paper jam							
<b>After change</b>	Paper jam  Careful for Drum							

## Firmware Details

Type	Program No.	File Name (after uncompressing)
MAIN	2BJ29278K	P2BJ2927.8K1
MMI	2BJ29289L	P2BJ2928.9L0
LANGUAGE E	2BJ29305F	P2BJ2930.5F2

When upgrading firmware, please upgrade 3 types of firmware (MAIN, MMI and LANGUAGE) to the newest version at the same time.

### Affected Machine Serial Numbers:

**KM-2530:** H3077775 and later  
**KM-3530:** J3053599 and later  
**KM-4030:** N3011657 and later