


SB Number:	SB 2FZ-030	Creation Date: 07/07/2008
Subject:	Coloured stripe trough the image	
Model:	KM-C2520/3225/3232/2525E/3232E/4035E	

Phenomenon	<p>A coloured stripe may appear on the image.</p> <p>See below for further details.</p>
-------------------	---

Cause	<p>Mylar is deformed and makes contact with the developer unit due to incorrect handling of the developer unit.</p> <p>See below for further details.</p>
--------------	---

Solution	Be careful not to touch the mylar film when handling the developer unit.
-----------------	--

A coloured **stripe** appears on the image.



Do not touch the **mylar** film when handling a developer unit

