



## *Service Bulletin*

Issued by Canon Europa N.V.

**LBP**  
**Hardware**

---

**Model:**

**LBP-2410**

**LBP-5200**

**Ref No.:**

LBP-1322

**Date:**

June, 2006

---

**Location:**

Parts Catalog LBP-2410/5200

**Subject:**

Incorrect part number

**Detail:**

Figure 530, Rotary Assembly, Key no. 7, Bushing

Incorrect: RB2-2908-000, Bushing

Correct: RB2-9808-000, Bushing