


<b>SB Number:</b>	<b>SB 2HP-009</b>	<b>Creation Date: 07/07/2008</b>
<b>Subject:</b>	<b>Coloured stripe trough the image</b>	
<b>Model:</b>	<b>FS-C8100DN</b>	

<b>Phenomenon</b>	<p>A coloured stripe may appear on the image.</p> <p>See below for further details.</p>
-------------------	---

<b>Cause</b>	<p>Mylar is deformed and makes contact with the developer unit due to incorrect handling of the developer unit.</p> <p>See below for further details.</p>
--------------	---

<b>Solution</b>	Be careful not to touch the mylar film when handling the developer unit.
-----------------	--

A coloured **stripe** appears on the image.



Do not touch the **mylar** film when handling a developer unit

