

<i>SB Number:</i>	SB 2G4-001	<i>Creation Date:</i> 02/08/2006
<i>Subject:</i>	<i>Network firmware upgrade, Ver. 1.2.0</i>	
<i>Model:</i>	FS-1016MFP	

Firmware Ver.1.2.0

When printing to an FS-1016MFP while the top cover is opened and a print job is received (during sleep mode), printing does not start even after the top cover is closed again. This problem is now fixed.

Field Measure:

If the problem arises, please upgrade firmware.