

<b>SB Number:</b>	<b>SB 2M0-001</b>	<b>Creation Date: 25/03/2011</b>
<b>Subject:</b>	<b>Firmware upgrade (Main v002.002, Fax boot/APL vN05.001)</b>	
<b>Model:</b>	<b>FS-1024MFP/1124MFP</b>	

	<b>Item</b>	<b>Contents</b>
1	DP count reset	The DP count reset function has been added to maintenance mode U002 (Factory setting)
2	Added country code	The country code for Russia has been added.

**Firmware**

<b>Type</b>	<b>Program No.</b>	<b>Check SUM</b>	<b>Version</b>	<b>Applicable model(s)</b>
MAIN	2L9_2F00.002.002	----	002.002	FS-1024MFP
MAIN	2M0_2F00.002.002	----	002.002	FS-1124MFP
ENGINE	2L9_1000.001.001	----	001.001	FS-1024MFP/1124MFP
SCANNER	2L9_1200.001.001	----	001.001	FS-1024MFP/1124MFP
FAX BOOT/APL	2H9_5500.N05.001	43961	N05.001	FS-1124MFP

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	Please upgrade the firmware to the latest version to implement the above mentioned changes.			

**Serial numbers of affected machines**

<b>Type</b>	<b>Serial number</b>
FS-1024MFP/1124MFP	February 2011 production.

The above mentioned changes have been applied to machines produced after the above mentioned production date.