

SB Number:	SB 2H4-007	Creation Date: 02/02/2010
Subject:	<i>Firmware upgrade (connection failure with the command center)</i>	
Model:	FS-1350DN	

Phenomenon

Connection failure with the command center may occur.

Firmware

Type	Program No.	Check SUM	Version	Status Date
SYSTEM	2H4_3000006003	36ba	006.003	02/11/2009
ENGINE	2H4_1000005001	1069	005.001	21/10/2009

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please upgrade the firmware to the latest version.			

Serial numbers of affected machines

Type	Serial number
FS-1350DN	Not available