

SB Number:	SB 2H4-004	Creation Date: 01/10/2009
Subject:	<i>Firmware upgrade (messages when the paper runs out during mixed sized printing)</i>	
Model:	FS-1350DN	

Phenomenon	The messages “add paper” and “processing” may be alternately displayed, when the paper cassette runs out of paper during mixed sized printing.
-------------------	--

Solution	The engine firmware has been corrected.
-----------------	---

Firmware	Type	Program No.	Check SUM	Version	Status Date
	ENGINE	2H4_1000004002	8e80	004.002	24/07/2009

Field measure	When the above mentioned phenomenon occurs, please upgrade the firmware to the latest version.
----------------------	--

Affected serial numbers	Type	Serial number
	FS-1350DN	Not available