

<b>SB Number:</b>	<b>SB 2HS-001</b>	<i>Creation Date: 17/04/2008</i>
<b>Subject:</b>	<b><i>Engine firmware upgrade (version 003.001) (Display error code 0000 instead of error code 0150)</i></b>	
<b>Model:</b>	<b>FS-1300D</b>	

<b>Phenomenon</b>	When the controller fails to communicate with the EEPROM on the controller board during power up diagnosis, error code 0150 should be displayed. Instead error code 0000 (Unknown error code) will be displayed.
-------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Firmware</b>	<b>Type</b>	<b>Program No.</b>	<b>Check SUM</b>	<b>Version</b>	<b>Status Date</b>
	ENGINE	S2HS_1000003001	358E	003.001	22/01/2008

<b>Field measure</b>	Upgrade the firmware.
----------------------	-----------------------

<b>Affected serial numbers</b>	<b>Type</b>	<b>Serial number</b>
	FS-1300D	Production from March 2008 and later.