

<b>SB Number:</b>	<b>SB 2G4-005</b>	<b>Creation Date: 16/04/2009</b>
<b>Subject:</b>	<b><i>Firmware upgrade V1.69A/2.13F (scanner lamp stops during copy job after sleep mode recovery)</i></b>	
<b>Model:</b>	<b>FS-1016MFP/1116MFP</b>	

<b>Phenomenon</b>	The scanner lamp (exposure lamp) may stop during a copy job, when scanning the right side of the original. This occurs after the machine recovers from a 2 hours or more sleep mode period.
-------------------	--

<b>Firmware version</b>	<b>Applicable machine</b>	<b>Type</b>	<b>Program No.</b>	<b>Check SUM</b>	<b>Version</b>
<b>1.69A /2.13F</b>	FS-1016MFP	SYSTEM	3in1_169A_char	----	V1.69A
	FS-1116MFP	SYSTEM	4in1_213F_char	----	V2.13F

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomenon occurs, please upgrade the controller firmware to the latest version.			

<b>Affected serial numbers</b>	<b>Type</b>	<b>Serial number</b>
	FS-1016MFP/1116MFP	March 2009 production