


# Service Bulletin

|             |                         |
|-------------|-------------------------|
| Ref. No. :  | <b>SB-00173</b>         |
| Issue Date: | <b>January 18, 2001</b> |
| Model Name: | <b>FS-1800, FS-3800</b> |

|           |          |           |              |                      |                     |
|-----------|----------|-----------|--------------|----------------------|---------------------|
| 1.Subject | 2.Reason | 3.Details | 4.Serial No. | 5.Interchangeability | 6.Parts name & code |
|-----------|----------|-----------|--------------|----------------------|---------------------|

- Change of screw for Fuser Unit.
- 
- Bind head screw (M3x4) with spacer was used to fit the solenoid. Stud screw replaces the screw and spacer.



- |    |  |  |
|----|--|--|
| 4. | <b>FS-1800</b><br>AAB0X15251 and up<br>AKB0X02701 and up<br>ASY0X00202 and up:<br>ABA0X00051 and up.   | <b>FK-60</b><br>GBC0X21983 and up.<br>GBC0X21983 and up.<br>GBC0X21983 and up.<br>GBC0X21983 and up.<br>GBC0X21983 and up.<br>GBD0X00148 and up. |
|    | <b>FS-3800</b><br>AAC0X05703 and up.<br>AKC0X00601 and up.<br>ASZ0X00002 and up.<br>ABB0X00041 and up. | <b>FK-61</b><br>GBE0X10620 and up.<br>GBE0X10620 and up.<br>GBE0X10620 and up.<br>GBE0X10620 and up.<br>GBE0X10620 and up.<br>GBF0X01644 and up. |

- Yes.
- Part name and part code is changed as follows.

|     | REF. NO. | Part name       | Part code    |
|-----|----------|-----------------|--------------|
| Old | I1       | BIND HEAD SCREW | 5MBSPB3004NZ |
|     | 06-B10   | SPACER          | 5MMM140SZ015 |
| New | 06-B10   | STUD SCREW M3   | 5MMT143SZ014 |