


Service Bulletin

Ref. No. :	SB-00174
Issue Date:	January 18, 2001
Model Name:	FS-1800, FS-3800

1.Subject	2.Reason	3.Details	4.Serial No.	5.Interchangeability	6.Parts name & code
-----------	----------	-----------	--------------	----------------------	---------------------

1. Change of color of LEVER LOCK.
2. For customer's requirement.
3. Change of color of LEVER LOCK from white to green.



- | | | |
|--|---|---|
| <ol style="list-style-type: none"> 4. | <p>FS-1800
 AAB0Y17291 and up.
 AHB0Y01501 and up.
 AYE0Y00601 and up.
 AKB0Y03701 and up.
 ASY0Y00402 and up.
 ABA0Y00553 and up.</p> <p>FS-3800
 AAC0X06595 and up.
 AHC0Y01501 and up..
 AKC0X00601 and up.
 ASZ0Y00202 and up
 ABB0Y00342 and up.</p> | <p>FE-60
 GKA0X26275 and up.
 GKA0X26275 and up.</p> <p>FE-61
 GKB0X08976 and up.
 GKB0X08976 and up.</p> |
|--|---|---|

5. Yes.
6. There is no changed for part name and part code.

REF. NO.	Part name	Part code
05-004	LEVER LOCK	5MVX666SH005