

SB Number:	SB 2FP-010	Creation Date: 22/02/2006
Subject:	<i>Firmware upgrade, Ver. A009 (engine)</i>	
Model:	FS-3820N	

The firmware is upgraded as follows.

For production efficiency, the system default value of engine parameter offset 5 (feed clutch timing) has been changed to 1. Previously it was manually set to 1 in the production process.

Type	Program number	Check SUM	Version	Remarks
ENGINE	EB28KA009	5090	A009	

Field Measure:

If the problem arises, please upgrade firmware.

Affected machine serial numbers:

ALD5X43307 and higher.