

SB Number:	SB 2F8-012	Creation Date: 20/09/2006
Subject:	<i>Firmware upgrade, Ver. 007.001/007.003 (engine/system)</i>	
Model:	FS-3900DN	

Engine Firmware is upgraded as follows.

A paper jam which may occur when changing paper source to the bulk feeder has been corrected.

Type	Program number	Check SUM	Version
ENGINE	S2F9_1000007001	FEA8	007.001

System Firmware is upgraded as follows.

Malfunctions corrected

1. Operation panel button lock-up that may occur if the cancel button is pushed when a paper jam occurs.
2. F030 error that may occur when direct printing a PDF file.

Type	Program number	Check SUM	Version
System	2F9_3000007003	BF04	007.003