

SB Number:	SB 2F8-011	Creation Date: 20/09/2006
Subject:	Firmware upgrade, Ver. 006.001/007.003 (engine/system)	
Model:	FS-4000DN	

Engine Firmware is upgraded as follows.

A paper jam which may occur when changing the paper source to the bulk feeder is corrected.

Type	Program number	Check SUM	Version
ENGINE	S2GA_1000006001	3847	006.001

System Firmware is upgraded as follows.

Malfunctions corrected

1. Operation panel button lock-up that may occur if the cancel button is pushed when a paper jam occurs.

Condition under which the phenomenon occurs:

- A. Buzzer on the panel is set to "OFF".
- B. The cancel button is pushed while paper is jammed.

2. F030 error that may occur at PDF direct print.
F030 error may sometimes occur when printing certain PDF files.
*There is no problem that buzzer is "ON".

Type	Program number	Check SUM	Version
System	2F9_3000007003	BF04	007.003