

SB Number:	SB 2F8-016	Creation Date: 15/01/2007
Subject:	Firmware upgrade, Ver. 008.001/008.002/009.002 (engine)	
Model:	FS-2000DN/3900DN/4000DN	

The firmware is upgraded to solve the following issues:

Refilled toner detection is implemented.

- * When refilled toner is installed, "Unknown toner installed" is indicated
- * Explanatory drop-in sheet is added to the replacement toner carton. This will guide the customer through the steps which need to be taken when the "Replace toner" message appears.

The main charge voltage is adjusted for use in high temperature and high humidity. This will avoid corrupted images if the drum surface should become moist/ wet.

Type	Program number	Check SUM	Version	Remarks
ENGINE	S2F8_1000008001	80D2	008.001	FS-2000DN
ENGINE	S2F9_1000009002	16D6	009.002	FS-3900DN
ENGINE	S2GA_1000008002	62DE	008.002	FS-4000DN

Field measure:

Should the problem arise please update the firmware.