

SB Number:	SB 2F8-010	Creation Date: 20/10/2006
Subject:	Firmware upgrade, Ver. 005.002 (system) resolving F030	
Model:	FS-2000D	

System Firmware is upgraded as follows.

1. Operation panel button lock-up that may occur if the cancel button is pushed when a paper jam occurs.

Condition under which the phenomenon occurs:

- A. Buzzer on the panel is set to "OFF".
- B. The cancel button is pushed while paper is jammed.

2. F030 error that may occur at PDF direct print.
F030 error may sometimes occur when printing certain PDF files.
*There is no problem that buzzer is "ON".

Type	Program number	Check SUM	Version
System	2F8_3000005002	D65F	005.002

Field measure:

If the problem arises, please upgrade firmware.