


SB Number:	SB 2F8-025	Creation Date: 18/02/2009
Subject:	Improper detection of the empty paper cassette	
Model:	FS-2000D/3900DN/4000DN	

Phenomenon	Improper detection of paper empty.
-------------------	------------------------------------

Cause	Marker indicator 302F909260 does not go down to the bottom of the paper cassette.
--------------	---

Solution	The shape of the cover lift gear has been changed.
-----------------	--



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
					Old	New	Old	New	
FS-2000D	1	302F809040 2F809040	302F809041 2F809041	+COVER LIFT GEAR	1	1	O	O	-
FS-3900DN/ 4000DN	2	302F909230 2F90923	302F909231 2F909231	+COVER LIFT GEAR	1	1	O	O	-