

SB Number:	SB 2F8-005	Creation Date: 02/08/2006
Subject:	<i>Firmware upgrade, Ver. 005.001/004.001 (engine/system)</i>	
Model:	FS-2000D	

Engine firmware (Ver. 005.001)

An insufficient Developer Bias voltage may cause a gray background or horizontal line. This problem has been rectified.

Type	Program number	Check SUM	Version
ENGINE	S2F8_1000.005.001	A45F	005.001

System firmware (Ver. 004.001)

Engine firmware is now available for download through network.

TYPE	Program number	Check SUM	Version
SYSTEM	S2F8_3000.004.001	F45F	004.001

Field Measure:

If the problem arises, please upgrade firmware.