

<b>SB Number:</b>	<b>SB 2MF-001</b>	<b>Creation Date: 05/10/2011</b>
<b>Subject:</b>	<b>Firmware upgrade (Main v003.008)</b>	
<b>Model:</b>	<b>FS-3040MFP+/3140MFP+</b>	

Item	Contents
1 POP/SMTP support	Email printing and SSL transmission are now supported.
2 IB-23 support	The IB-23 is now supported.

#### Firmware

Type	Program No.	Check SUM	Version	Applicable model(s)
ENGINE	2LW_1000.004.001	6EAA	004.001	FS-3040MFP+/3140MFP+
<b>MAIN</b>	2MF_2F00.003.008	-----	003.008	FS-3040MFP+
<b>MAIN</b>	2MG_2F00.003.008	-----	003.008	FS-3140MFP+
SCANNER	2MG_1200.001.015	-----	001.015	FS-3040MFP+/3140MFP+
FAX BOOT/APL	2H9_5500.006.001	-----	006.001	FS-3140MFP+

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomena occur, please upgrade the firmware to the latest version.			

#### Serial numbers of affected machines

Type	Serial number
FS-3040MFP+/3140MFP+	August 2011 production.

The above mentioned changes have been applied to machines produced after the above mentioned production date.