

# Service Bulletin

SB Number:	SB 2B0-008	Creation Date:	30/08/2003
Subject:	Change Engine ROM version (A016 => A017)		
Model:	FS-3800(N)		

Firmware has been changed to correct the below phenomenon.

## Phenomenon

Paper may jam when printing legal paper in duplex at low print coverage.

## A016 => A017

	ROM Ver.	Checksum	Label Name	U-No	Rom Type
Engine	A017	A772	E38KA017	U3	2 Mbit-Flash ROM

## Field Measure

Please upgrade the firmware if the phenomenon should arise.

### Affected Machine Serial Numbers:

**FS-3800:** AAC3743860 and later