


<b>SB Number:</b>	<b>SB 2BZ-005</b>	<b>Creation Date: 20/01/2009</b>
<b>Subject:</b>	<b>Deformed seal discharger in the fuser unit</b>	
<b>Model:</b>	<b>FS-6020</b>	

<b>Phenomenon</b>	The seal discharger in the fuser unit may deform to a point, where it damages the press roller.
-------------------	---


<b>Cause</b>	Poor assembly of the seal discharger.
--------------	---------------------------------------

<b>Solution</b>	The phenomenon has been detected in the FK-400 fuser units supplied between February 2008 and August 2008.
-----------------	--

Phenomenon; The deformed **seal discharger** on the **frame fuser low** may damage the **roller press**



Back view of the deformed seal discharger



Parts	No.	Parts No.	Description	Q'TY To be shipped	Your order number
	1	5PLPXRQAXKX	FK-400(E) /FUSER UNIT	1	KME-080519

<b>Shipping information</b>	Replacement parts will be shipped by the KME-RPS department accordingly.
-----------------------------	--