


<b>SB Number:</b>	<b>SB 2KW-001</b>	<b>Creation Date:</b> 15/09/2010
<b>Subject:</b>	<b>Replacing the DR-590B drive unit</b>	
<b>Model:</b>	<b>FS-C2026MFP/2126MFP</b>	

When replacing the **DR-590B drive unit** please check if 2 pieces of the **shim** are attached to 1 of the **DR-590B gears**. If this is the case, please remove the **shims** and install the **DR-590B**.



<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
<b>Field measure</b>	When replacing the <b>DR-590B drive unit</b> please check if 2 pieces of the <b>shim</b> are attached to 1 of the <b>DR-590B gears</b> . If this is the case, please remove the <b>shims</b> and install the <b>DR-590B</b> .			

### Serial numbers of affected machines

Type	Serial number
FS-C2026MFP/2126MFP	August 2010 production

The above mentioned changes have been applied to machines produced after the above mentioned production date.