

SB Number:	SB 2HG-007	Creation Date: 01/04/2010
Subject:	Firmware upgrade (Engine firmware version 007.001)	
Model:	FS-C5400DN	

The engine firmware has been changed as follows:

1. The toner density control will be adjusted according to the page count so that the toner charge level will be stabilized.
2. The toner replenishment interval will be adjusted according to the print coverage so that the toner charge level will be stabilized.
3. To prevent decreased toner density on the image when the toner is depleted, the developer bias has been adjusted.

Firmware

Type	Program No.	Check SUM	Version	Status Date
SYSTEM	2HG_3000005017	2da9	005.017	21/10/2009
ENGINE	2HG_1000007001	134d	007.001	15/01/2010

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	To implement the above mentioned changes, please upgrade the firmware to the latest version.			

Serial numbers of affected machines

Type	Serial number
FS-C5400DN	Not available