


SB Number:	SB 2HN-001	Creation Date: 18/02/2009
Subject:	<b>Black toner contamination at the main charger</b>	
Model:	<b>FS-C5100DN/5200DN/5300DN</b>	

<b>Phenomenon</b>	The non-printable area of the main charger may become contaminated with black toner.
-------------------	--

<b>Solution</b>	Add sheet front 302HN02980 at the frame front.
-----------------	--



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	-----	302HN02980 2HN02980	SHEET FRONT	1	1	O	O	-