

SB Number:	SB 2HG-008	Creation Date: 01/04/2010
Subject:	<i>Firmware upgrade (To improve the accuracy of the power-up calibration patch)</i>	
Model:	FS-C5400DN	

To improve the accuracy of the power-up calibration patch image, the engine firmware has been upgraded.

Firmware

Type	Program No.	Check SUM	Version	Status Date
SYSTEM	2HG_3000005017	2da9	005.017	21/10/2009
ENGINE	2HG_1000008002	1c6a	008.002	18/02/2010

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	Please upgrade the firmware to the latest version to implement the above mentioned change.			

Serial numbers of affected machines

Type	Serial number
FS-C5400DN	XAC0201219

The above mentioned change has been applied to machines produced after the above mentioned serial number.