

Service Bulletin

SB Number:	SB 03-002	Creation Date: 27/08/2003
Subject:	Zero-sec recovery / recovery priority mode discontinued	
Model:	KM-6330, KM-4530, KM-5530, KM-2530, KM-3530, KM-4030, KM-4850w, KM-P4845w, KM-P4850w, KM-S4850w	

Please be informed that due to environmental reasons, the service simulations related to 'zero-sec. recovery' and 'recovery priority mode' have been discontinued. In addition, the firmware has been changed so that the transition time to auto preheat can be set to a longer period.

CONTENTS OF CHANGES

- **SIM 344** (= 'Setting preheat/energy saver mode'): selection of the zero-sec. recovery deleted.
- **SIM 256** (= 'Turning auto preheat/energy saver function on/off) deleted.
- Auto preheat setting has been changed.

KM-6330:	for more details please refer to SB 2CJ-007 .
KM-4530, KM-5530:	for more details please refer to SB 2BC-014 .
KM-2530, KM-3530, KM-4030:	for more details please refer to SB 2BJ-021 .
KM-4850w:	for more details please refer to SB 2A7-022 .
KM-P4845w, KM-P4850w, KM-S4850w:	for more details please refer to SB 2A7-023 .

IMPORTANT NOTE / FIELD MEASURE for KM-2530 / 3530 / 4030

In the KM-2530 / 3530 and KM-4030, the preheat mode can be set to ON or OFF in simulation **U256**. Please pay attention however that should this preheat setting in the above models must not be set 'OFF', as these models have acquired the Energy Star standard, which requires preheat setting to be on!

Therefore, if the customer demands to change the preheat setting to 'OFF', please kindly explain the above point to the customer and change the setting to 'ON'. If the setting should be set to 'OFF', please change the setting back to 'ON'. The factory default setting for the preheat is set to 15 minutes.

Affected Machine Serial numbers:

KM-2530:	H3039888 and later
KM-3530;	J3033348 and later
KM-4030:	N3006487 and later
KM-4530:	C3009236 and later
KM-5530:	D3009580 and later
KM-6330:	Z3001426 and later
KM-4850w:	L0001769 and later
KM-P4850w:	N0000263 and later
KM-P4845w:	next production
KM-S4850w:	P0000347 and later