

<b>SB Number:</b>	<b>SB 2JB-002</b>	<b>Creation Date: 17/04/2008</b>
<b>Subject:</b>	<b><i>F/W Change (Preventing white spots at the leading edge and change image transfer timing)</i></b>	
<b>Model:</b>	<b>KM-2540/3040, Printing system Y</b>	

Contents of changes	Item	Contents
	Preventing white spots from appearing at the leading edge.	The timing between charging and discharging has been changed.
	Image transfer timing has been changed.	The image transfer timing has been changed to improve printing near the leading edge.

Latest firm-ware as of February 2008	Type	Program No.	Check SUM	Version	Status Date
	MAIN	2JB_2000004001	----	004.001	
	ENGINE	2JB_1000007002	----	007.002	
	LANGUAGE E	2JB_81XE001003	6FB3	001.003	
	PRINTER FS	2JC_3F00.002.001	147D	002.001	

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomenon occurs, please upgrade all the firmware to the newest version.			

Affected serial numbers	Type	Serial number
	KM-2540	QAL7Y01128 and higher
	KM-3040	QAQ7Y01043 and higher
	Printing system Y	URG7Y01449 and higher