

<b>SB Number:</b>	<b>SB 2G1-010</b>	<b>Creation Date: 19/03/2008</b>
<b>Subject:</b>	<b><i>Firmware upgrade (Incorrect toner coverage data)</i></b>	
<b>Model:</b>	<b>FS-9130DN/9530DN</b>	

Contents of changes	
Item	Remark
Preventing incorrect toner coverage data	Incorrect calculation of the toner coverage data.

**Example of toner coverage on the status page:**

19.9 (Toner coverage (%) Average)/ 2500000.0, this value may be incorrect.  
4.0 (Toner coverage (%) Last page)

Latest firmware as of October 2007				
Type	Program No.	Check SUM	Version	Status Date
ENGINE	S2G1_1000.013.001	57D7	013.001	09/10/2007
MAIN	S2G1_3000.007.001	D663	007.001	19/07/2007

**Field measure:**

If above mentioned phenomenon occurs, upgrade the firmware to the newest version.

Affected machine serial numbers
From the production of October 2007