

<b>SB Number:</b>	<b>SB 2G1-023</b>	<b>Creation Date: 02/02/2010</b>
<b>Subject:</b>	<b>Firmware upgrade (numonyx flash memory and stapling job print-out failure)</b>	
<b>Model:</b>	<b>FS-9130DN/9530DN</b>	

**Content of changes**

	<b>Item</b>	<b>Contents</b>
1	Numonyx flash memory.	Because the commonly used spansion flash memory has become difficult to obtain, we changed the common type to numonyx flash memory. The system firmware has been upgraded to support the numonyx flash memory. Please note that the firmware is backward compatible with older flash memory.
2	Print-out failure.	Printing may stop while the machine is processing jobs with a mixed number of stapled pages.

**Firmware**

<b>Type</b>	<b>Program No.</b>	<b>Check SUM</b>	<b>Version</b>	<b>Status Date</b>
MAIN	S2G1_3000.013.001	C81A	013.001	13/10/2009
ENGINE	S2G1_1000.019.001	916C	019.001	11/20/2009

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomenon occurs and to support the numonyx flash memory, please upgrade the firmware to the latest version.			

**Serial numbers of affected machines**

<b>Type</b>	<b>Serial number</b>
FS-9130DN/9530DN	December 2009 production

Machines produced after the above mentioned production date, should be affected by the above mentioned changes.