


SB Number:	SB 2G1-019	Creation Date: 27/11/2008
Subject:	The magnet disengages from the front cover	
Model:	FS-9130DN/9530DN	

Phenomenon	The magnet disengages from the magnet catch in the cover center front, when opening it.
-------------------	---

Solution	<p>The following changes have been made to prevent the magnet from disengaging from the magnet catch.</p> <ol style="list-style-type: none"> 1. The shape of the magnet catch has been changed. 2. The shape of the attachment position for the magnet catch has been changed.
-----------------	--

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
					Old	New	Old	New	
	1	2FB04220	302H004660 2H004660	MAGNET CATCH	1	1	X	X	-
	2	302GR04021 2GR04021	302GR04022 2GR04022	COVER CENTER FRONT	1	1	X	X	O



Classification	<input type="checkbox"/> Entire stock rework <input type="checkbox"/> In-field modification at next visit <input checked="" type="checkbox"/> In-field modification by case <input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please replace magnet catch 2FB04220 with 302H004660 and cover center front 302GR04021 with 302GR04022.

Affected serial numbers	Type	Serial number
	FS-9130DN/9530DN	March 2008 production