

<b>SB Number:</b>	<b>2G1-015</b>	<b>Creation Date: 17/04/2008</b>
<b>Subject:</b>	<b>Machine lock after recovering from sleep mode</b>	
<b>Model:</b>	<b>FS-9130DN/9530DN</b>	

Contents of changes	Item	Contents
	Machine lock after recovering from sleep mode.	The machine may lock after recovering from sleep mode, while the message "please wait" is displayed on the panel.

Latest firm-ware as of September 2007	Type	Program No.	Check SUM	Version	Status Date
	ENGINE	S2G1_1000.010.001	777D	010.001	30/08/2007
	MAIN	S2G1_3000.007.001	D663	007.001	19/07/2007

<b>Field measure</b>	When the above mentioned phenomenon occurs, please upgrade the firmware to the latest version.
----------------------	------------------------------------------------------------------------------------------------

Affected serial numbers	Type	Serial number
	FS-9530DN	PAS7702361 and higher