J - Transport Sensor Location

NOTE: See **J-Transport Sensor Functions** for description of sensor functions.

- F-Trans Path Sensor #4
- J-Trans Path Sensor #1
- J-Trans Path Sensor #4
- J-Trans Path Sensor #5
- J-Trans Path Sensor #3
- Tray 3 Feed Out Sensor
- Tray 3 Path Sensor
- Aligner Path Sensor #1
- J-Trans Dup Sensor #3
- J-Trans Dup Sensor #1
- H-Trans Path Sensor #8