Canon

Service Bulletin

Issued by Canon Europa N.V.

Model:	**Ref No.:**
LaserBase MF5730	MF5650-007 Rev. 1
LaserBase MF5750	(SH-T01-0LD-10025-02)
	Date:
	October 2005

Location:

SCNT Board Assembly (HG3-3999/ HG3-4000)

Subject:

Version upgrade of main ROM for SCNT board assembly (WLaa-55-08)

SPEED:

SH-LD-0033-01

Destination:

F14-6532 (US,CA/120V), F14-6592 (GB,FR,CN,KR/230V), F14-6531 (US,CA/120V), F14-6591 (GB,FR,CN,KR/230V)

Reason:

Upgrade the version of firmware for SCNT board assembly from WLaa-54-62 to WLaa-55-08.

History of upgrade:

Service Bulletin	Ver.	Detail	Date
	WLaa-55-08	Change of the default value in network setting	May 27, 2005
SH-T01-0LD-10012-01	WLaa-54-62	Countermeasure against the vertical lines which occur when scanning originals into computer	Nov. 4, 2004
None	WLaa-54-52	First release	

Detail:

No.	Item	Detail
1	Change of the default value in network setting	Change the default value in network setting so that it can be used commonly for all destinations IPAUTO: OFF > ON, DHCP: OFF >ON

Service parts:

No.		Part name	Part No.	Qty	Stock	Compati-bility	Available from	Fig. No.
1	Old	SCNT BOARD ASS'Y	FG3-3997-000	1 > 0	C	N		950
	New	SCNT BOARD ASS'Y	FG3-3997-030	0 > 1	D	Y		
2	Old	SCNT BOARD ASS'Y	FG3-3996-000	1 > 0	C	N		950
	New	SCNT BOARD ASS'Y	FG3-3996-030	0 > 1	D	Y		

Effective on:

March 2005

Serial No.:

Model		Starting Serial No.
imageCLASS MF5730	(USA)	KLU02489
imageCLASS MF5750	(USA)	KLV15725
imageCLASS MF5730	(CND)	KLX02237
imageCLASS MF5750	(CND)	KLY03193