KYOCERA

Service Bulletin

SB Number:	**SB PF-008**	Creation Date: **13/10/2004**
Subject:	Counter value [9999999] at setup	
Model:	**PF-410**	

PF-410: *Paper feeder for KM-1620 / 2020.*

Phenomenon

The counter value might be [9999999] at the delivery of PF-410.

Cause

If after installing EEPROM to PCB in the production lines, the first startup is performed in checker mode, the counter value becomes [9999999] and data is not initialized. Then, if 8 sheets or more are output without turning the power off, the counter value is continuously counted from the next value. However, if the power is turned off before outputting 8 sheets of paper, the counter value returns to [9999999].

Field Measure

Please check the counter value at setup! If the phenomenon arises, please clear the counter value with maintenance mode **U901** (= '*Checking / clearing counts by paper feed locations*').